

Dear Users,

The 3.20 version of BAT-EMC software represents more than 3000 hours of conception and solves more than 200 bugs, together with more than 500 hours of validation.

BAT-EMC Visu V4



Metrology



Mast and Turntable Control



Visu V4: New Emission Test Execution Module

- Max Hold measurement integrated
- Test definition backward compatibility
- Antenna Mast/Turntable Control

New Report Generation:

- Up to 20x faster
- New template tags with more flexibility
- Including emission, immunity and all other type of test

New Test Type:

- HVLV CISPR 25 Hybrid
- Metrology measurements performed with a VNA and Oscilloscope.
- Transient Test
- Sensibility Radio Test

Other Improvements:

- TDEMI Continuous measurement with spectrogram and real time analyzer
- Save the fault message list.
- Mast and turntable speed control for Emissions Test (Advanced Prescan and Advanced Finals)
- Possibility to control the turntable for the multisensory calibration.
- Reverb: Add MIL-STD Methods
- The manual is updated with each new version

You can find at the end of the document all modifications in this new version.

The validation was made between the 1st of February 2020 to the 15th of April 2020. This validation was done by everybody of the team, as well as the developers:

Sébastien AUROUX, Baptiste CRESPI, Guy DASSONNEVILLE, Maxime BLIN, Eric ARNOULD, Vincent HELBERT, Simon FROIDEFOND, Hartmut BEYER, Greg GARZA and Sébastien MARTINEAU.

BAT-EMC Team hopes you enjoy the reading.

Validation Procedure

Validating a BAT-EMC new version is not an easy task because:

- BAT-EMC software is highly configurable. Once delivered, users keep setting it up in order to adapt it to their own needs or to their methods evolution.
- BAT-EMC software drives many instruments, more than 350, and we do not have all equipment in our office.

Validation must be done with in three stages:

- An **office validation** (standard configuration without instruments)
- An **office validation** (in our laboratory with a few instruments)
- An **onsite validation** (laboratory configuration with instruments).

Concerning maintenance, NEXIO performs office validation. Onsite validation is charged to customers. NEXIO proposes this validation as an option.

3.20 version office validation has been realized following this procedure:

- Automatic non-regression testing with a validation tool,
- Manual validation of modifications,
- Manual validation of non-regression,
- Documentation verification.

The automatic non-regression testing aims to compare for each new version that the result of its execution and its report has not changed. Therefore, we use:

- A specific validation module that simulates the instruments, automatically continues testing, exports results and creates reports.
- A set of tests and configuration as representative as possible.

The results generated by the new version are compared to those obtained with the previous one.

The goal of that stage is mainly to validate:

- the considering and calculating of the transfer function (Emission and Immunity)
- methods and drivers leveling (Immunity)
- measurement algorithms (Prescan, suspect, finals) (Emission)
- results export

-reports creation

Non-regression manual validation completes the previous one and is used to test BAT-EMC non-automated major functions.

- Publication.
- Copy/paste.
- Creation of project, hardware, set-up, limits, instructions, calibration, tests...
- Standard import.
- Immunity manual mode.
- Backward compatibility of data (opening of project and hardware from the former version with the new one).

Manual validation of modifications is used to individually test all the new version modifications (anomalies or evolutions).

Non-regression automatic validation

This chapter explain the errors found during validation.

Comparison between exports and reports with the previous version is performed separately.

The second part of this document explain the differences if these differences came from a correction or modification of the software.

Report

Analysis-Conclusion

Version 3.19.1.18


Add in new version of a display parameter number before decimal point (ticket INC0013666)

| Suspect NB | | | | | | | | | | | |
|-----------------|------------------|-----------------|------------|---------------|---------------|-----------------|------------------|-----------------|-------------|-----------|-------|
| Frequency (MHz) | SR# | Peak (dBuV) | Avg (dBuV) | Peak-Avg (dB) | Q-Peak (dBuV) | Line Supply | RBW | NB-BB | Line Supply | RBW | NB-BB |
| 1,4 | 1 | 70,02 | 65,02 | 5,00 | 80,02 | 60,00 | 20,02 | Line Supply | RBW | NB-BB | 12 |
| 2,95 | 1 | 51,99 | 46,99 | 5,00 | 61,99 | Line Supply | RBW | NB-BB | 12 | 2,95 | 1 |
| 8,65 | 1 | 50,83 | 45,83 | 5,00 | 60,83 | Line Supply | RBW | NB-BB | 12 | 8,65 | 1 |
| Suspect NB | | | | | | | | | | | |
| Frequency (MHz) | SR# | Peak (dBuV) | Avg (dBuV) | Peak-Avg (dB) | Q-Peak (dBuV) | Line Supply | RBW | NB-BB | Line Supply | RBW | NB-BB |
| 1,4 | 1 | 70,02 | 65,02 | 5,00 | 80,02 | 60,00 | 20,02 | Line Supply | RBW | NB-BB | 12 |
| 2,95 | 1 | 51,99 | 46,99 | 5,00 | 61,99 | -10000000000,00 | -10000000000,00 | Li | 2,95 | 1 | 51,99 |
| 8,65 | 1 | 50,83 | 45,83 | 5,00 | 60,83 | -10000000000,00 | -10000000000,00 | Li | 8,65 | 1 | 50,83 |
| Frequency (MHz) | Meas.Peak (dBuV) | Meas.Avg (dBuV) | Position | SR Number | SR | Frequency (MHz) | Meas.Peak (dBuV) | Meas.Avg (dBuV) | Position | SR Number | SR |
| 0,15 | 41,97 | 36,97 | Supply 1 | 0,15 | 10 | 50kHz | 120kHz | Auto | OFF | 5 | 0,15 |
| 0,15 | 41,97 | 36,97 | Supply 1 | 0,15 | 10 | 50kHz | 120kHz | Auto | OFF | 5 | 0,15 |


Version 3.19.1.19

1/ Power disturbing emissions EN55013 PD

Problem in the database for some time (1 instead of 0 in the limit settings).



2/ Different results between this version and the previous ones (addition of the final 55013 + 55013 RS).
The problem is now resolved.



3.19.1.18

3.19.1.19

Manual validation of modifications

Annual validation is applied only on modification which can be tested without any drivers. Modifications regarding drivers are not performed by NEXIO but must be performed by the customer.

Configuration list

You can find below the list of evolution included in the 3.20 version.

| ID | Module | Summary | Severity | Version |
|--|--------------------|--|-----------|----------|
| CHG0030380 | BAT-EMI By Band | 1292: Extended Reports. Graph by band group. Management of breaking changes so that the template works with 2 versions. Possibility to make a relative path for sub reports. Activation Aspose InLineErrorMessage in Report Generation | Bug | 3.19.1.5 |
| INC0012734 | BAT-EMC | The Check ID command does not work on the equipment and returns timeout errors or unterminated query errors. Unicode Issue | Bug | 3.19.1.5 |
| CHG0030510 | BAT-EMC | Manual Update | Evolution | 3.19.1.5 |
| INC0012718 | BAT-EMC | Multi-edition issue for test types with no EUT distance (which is the case of the conducted test used in this incident) | Bug | 3.19.1.5 |
| INC0012722 | BAT-EMC | Problem for AVG 9k measured in AVG 120k | Bug | 3.19.1.5 |
| INC0012722 | BAT-EMC | Wizard For limits with RBWPeak! = RBWAvg option "Meas. 120k instead of 9k" is not taken into account | Bug | 3.19.1.5 |
| INC0012702 | BAT-EMC | Wizard problem for antenna base tests | Bug | 3.19.1.5 |
| INC0012655 | BAT-EMC | The wizard did not work anymore | Bug | 3.19.1.5 |
| INC0012715 | BAT-EMC | Follow up problem with element required: Prevents validation of the Follow-Up to crash | Bug | 3.19.1.5 |
| INC0012717 | BAT-EMC | Close button in MaxHold manual measurements window does not work | Bug | 3.19.1.5 |
| INC0012719 | BAT-EMC | Adding more log to understand runtime executions | Bug | 3.19.1.5 |
| INC0012669 | BAT-EMC | Possible modification of a read-only project. Consider IsPublished for IsModifiable | Bug | 3.19.1.5 |
| CHG0030497 | BAT-EMC | Add 33511 pulses. Remove MBN & BMW need more informations. Add Standard for PSA & Renault | Bug | 3.19.1.5 |
| INC0012578 | BAT-ELEC | CI220/230 waveform was not correct. Pulse shape was fixed. | Bug | 3.19.1.5 |
| CHG0030480 | BAT-SCAN | Modification Driver BAT-Scanner | Evolution | 3.19.1.5 |
| INC0012337 | BAT-EMC | Change unit sweep time MS2720C | Bug | 3.19.1.5 |
| INC0012696 | BAT-EMC | Fix multiline copy / paste in the grid of follow up. Fixed bug database creation new 'Exemptions'. Added "copy of ..." when duplicating a test in a folder (emission and immunity). Adding a space after the number of a project for the list of recent projects in the 'Local' menu | Bug | 3.19.1.5 |
| INC0012655 | BAT-EMC | Display and use of limits are confusing. In the wizard, separation of the Peak and Average columns. Limits with PeakRBW! = AverageRBW are allowed | Bug | 3.19.1.5 |
| INC0012627 | BAT-IMAGE | If BAT-IMAGE dongle connected in addition to the EMI Automotive with bands dongle, the test does not start. A bug of multi-key in Rockey4ND.cs | Bug | 3.19.1.5 |
| INC0012505 INC0012534 INC0012576 | BAT-EMC | Deleting the cache during the backup | Bug | 3.19.1.5 |
| INC0012679 | BAT-SCAN | Bug publish/import BAT-SCAN Test with discrete frequencies | Bug | 3.19.1.5 |
| INC0012643 | BAT-EMI By Band | The field "name" of the external equipment is in "readonly" | Bug | 3.19.1.5 |

| | | | | |
|--------------------------|--------------------|--|-----------|----------|
| INC0012616 | BAT-EMC | Issue displaying the table of suspects in the report | Bug | 3.19.1.5 |
| INC0012739 | BAT-EMC | Correction link Webex | Bug | 3.19.1.6 |
| INC0012750 | BAT-EMC | Wizard problem when the limit included a frequency step by default and we ask to measure in 120k instead of 9k. The default frequency step was not taken into account in the wizard. VSTS 1330 | Bug | 3.19.1.6 |
| INC0012802 | BAT-EMC | Used equipment for calibrations CRBM | Bug | 3.19.1.6 |
| INC0012778 | BAT-EMC | For conducted emissions, line is misspelled as ligne | Bug | 3.19.1.6 |
| INC0012724 | BAT-EMC | Bug Import / Extract / Publish if focus on an EMS test | Bug | 3.19.1.6 |
| CHG0030517 | BAT-EMC | Spurious measurement (Control tool for customer B.) | Bug | 3.19.1.6 |
| CHG0030505 | BAT-EMC | Change the limit to a test that already has results. Management of the addition of a limit: Association of existing prescans to the new band, Deletion prescans without limit if necessary, Recalculation of suspects if deletion or addition of limit, Correction results screen: loading results and combobox of the choice of bands | Evolution | 3.19.1.6 |
| INC0012803 | BAT-EMC | Monitoring => Adding a title to the graphs containing modulation, position and sub range if necessary | Bug | 3.19.1.6 |
| INC0012731 | BAT-EMC | Problem waiting result of FSH8 | Bug | 3.19.1.6 |
| INC0012799 | BAT-EMC | GT8888A_64 Modify the driver to use two devices one for Forward and one for Reverse | Bug | 3.19.1.6 |
| INC0012705 | BAT-EMC | FSP and FSV driver suspend did not work | Bug | 3.19.1.6 |
| INC0012758 | BAT-EMC | Last frequency problem with FFT with data reduction, Add the Preselector splitter | Bug | 3.19.1.6 |
| INC0012781 | BAT-EMC | When starting a test or subrange, the software asks if you want to "resume". Change to "Start" | Bug | 3.19.1.6 |
| INC0012771 | BAT-EMC | Problem driver scope if 2 identical scopes used | Bug | 3.19.1.6 |
| CHG0030380 | BAT-EMI By Band | VSTS 1321: Plot per band must display the correct curves corresponding to the definition of the limit | Bug | 3.19.1.6 |
| INC0012744 | BAT-ELEC | BAT-ELEC RS232 communication issue | Bug | 3.19.1.6 |
| INC0012748 | BAT-EMC | Piece of curve that does not appear | Bug | 3.19.1.6 |
| INC0012768 | BAT-EMC | NSA test: the ref level is not saved | Bug | 3.19.1.6 |
| CHG0030399 | BAT-EMC | Avoid errors due to log4cxx when rebuilding full solution | Bug | 3.19.1.6 |
| INC0012763 | BAT-EMC | Add the DLL E4440A_LAN inside of the solution | Bug | 3.19.1.6 |
| INC0012691 | BAT-EMC | Issue with overlapped frequencies in inclusion table and special dwell list | Bug | 3.19.1.6 |
| INC0012734 | BAT-EMC | On the reverb emissions procedure, it states OK or Annuler instead of OK or Cancel | Bug | 3.19.1.6 |
| INC0012716 | BAT-EMI By Band | Input protection in BAT-EMI Automotive by band edition multiple | Bug | 3.19.1.6 |
| INC0012746 | BAT-EMC | Modification opening project to decrease the necessary time. | Bug | 3.19.1.6 |
| INC0012748 INC0012706 | BAT-EMC | Problem discontinuity import curve sub range. If we import several curves in the same project the legend does not indicate all the curves | Bug | 3.19.1.6 |
| CHG0030363 | BAT-EMC | Multisensor reverb EUT calibration. Erase instant curves after angle change | Bug | 3.19.1.6 |
| INC0012716 | BAT-EMI By Band | Input protection | Bug | 3.19.1.6 |
| INC0012720 | BAT-EMC | Right click copy returns an error | Bug | 3.19.1.6 |
| CHG0030374 | BAT-EMC | Add AxisFieldTool to setup | Evolution | 3.19.1.6 |

| | | | | |
|------------|-----------------|--|-----------|----------|
| INC0012944 | BAT-EMC | Filling the database at the end of the run after exporting the results without opening them | Bug | 3.19.1.8 |
| INC0012936 | BAT-EMC | Linking the visibility of a setup with the tests associated with it. | Bug | 3.19.1.8 |
| INC0012849 | BAT-EMC | ESU hangs when using receiver continuous scan | Bug | 3.19.1.8 |
| INC0012929 | BAT-EMC | Close com and go to local when test finished | Bug | 3.19.1.8 |
| INC0012948 | BAT-ELEC | BAT-ELEC issue with UCS500 & High Voltage Surge & Short Tr | Bug | 3.19.1.8 |
| INC0012928 | BAT-EMC | Filling GetIDN field for Transient generator result in Bat-Elec not working | Bug | 3.19.1.8 |
| INC0012943 | BAT-EMC | Add advanced final in the antenna base emission test | Bug | 3.19.1.8 |
| INC0012875 | BAT-VISU | BAT-Visu toolbar modification for EMI reverb calibration | Bug | 3.19.1.8 |
| INC0012653 | BAT-EMC | Selected setup is not memorized. 1360 - SelectedSetup choice recording equipment problem on the appendix | Bug | 3.19.1.8 |
| INC0012401 | BAT-EMC | Generate monitoring graphs on closing if they are missing (bug of 1.17) | Bug | 3.19.1.8 |
| INC0012927 | BAT-ELEC | BAT-ELEC Issue driving TRA-3000 and UCS500N7 Ringwave | Bug | 3.19.1.8 |
| CHG0030543 | BAT-EMI By Band | New driver Keysight N9010B EXA | Evolution | 3.19.1.8 |
| INC0012921 | BAT-EMC | Visu-Monitoring does not display curves in decreasing sweep | Bug | 3.19.1.8 |
| INC0012895 | BAT-EMC | VisuMonitoring does not display modulation for CW/AM calibration | Bug | 3.19.1.8 |
| INC0012895 | BAT-EMC | Monitoring => Displays the modulation of the calibration, If one has a 1.2G-1.4GHz SB, in the combo it displays 1G-1G | Bug | 3.19.1.8 |
| INC0012897 | BAT-EMC | VisuMonitoring does not display curves when a channel is added to a graph during test execution (or at the end) when the unit is 'dBm' | Bug | 3.19.1.8 |
| CHG0030505 | BAT-EMI By Band | Change the limit to a test that already has results. Adding limit without using the wizard causes the crash of BAT-EMC again. Correction done + in the execution: decrease the size of some icons, symbol "?" for "Suspicious" | Evolution | 3.19.1.8 |
| INC0012904 | BAT-EMC | Problem of compilation in release in Nexio.MonitoringViewer, we considered the warnings as errors (parameter of the project) | Bug | 3.19.1.8 |
| INC0012907 | BAT-EMC | Error message when using Export All menu (test with monitoring channel) | Bug | 3.19.1.8 |
| INC0012904 | BAT-EMC | Monitoring graph is missing : Current on shunt [10mA - 100mA] | Bug | 3.19.1.8 |
| INC0012891 | BAT-EMI By Band | Aspose report crashes if selection of a limit that does not exist in a test | Bug | 3.19.1.8 |
| INC0012904 | BAT-EMC | Curves that were displayed using Fushia color are displayed in blue (Fushia is not available in new version and should be replaced by Magenta instead of blue) | Bug | 3.19.1.8 |
| INC0012902 | BAT-EMC | VisuMonitoring autoscale cause application crash if all data of the curve is over scale maximum | Bug | 3.19.1.8 |
| INC0012826 | BAT-EMC | Link to download Update does not redirect to the right place | Bug | 3.19.1.8 |
| INC0012780 | BAT-EMC | Removes the 'Export All' option for calibrations. Shows the unit correctly when exporting for the 'Export results' option at the calibration type level. | Bug | 3.19.1.8 |

| | | | | |
|------------|-----------------|--|-----------|----------|
| CHG0030074 | BAT-EMC | TDEMI Visa Continuous Measurement Beta | Bug | 3.19.1.8 |
| INC0012831 | BAT-EMC | Registry read issue: a 32-bit PC with BAT-EMC installed (32-bits) | Bug | 3.19.1.8 |
| INC0012653 | BAT-EMC | Selected setup is not memorized. 1328 - Selected equipments are not saved dans le choix du montage | Bug | 3.19.1.8 |
| INC0012874 | BAT-EMC | Can not display Sub range in Reverb Emission Tests in the Tree (Calibration and Test) | Bug | 3.19.1.8 |
| INC0012866 | BAT-EMC | Add function DeleteResults() for Radiation Diagram | Bug | 3.19.1.8 |
| CHG0030517 | BAT-EMC | Spurious measurement (Control tool for Bosch). Add Quick user's guide | Bug | 3.19.1.8 |
| CHG0030531 | BAT-EMC | Activation of logs (ERROR level) and Adding logs to the eSupport zip | Bug | 3.19.1.8 |
| INC0012767 | BAT-EMC | Modification of the driver to always redo the init for the fieldmeters | Bug | 3.19.1.8 |
| INC0012636 | BAT-EMC | Removed the possibility to publish already published 'Setup' | Bug | 3.19.1.8 |
| INC0012844 | BAT-EMC | Input/Coupling did not show in the ESW settings | Bug | 3.19.1.8 |
| INC0012811 | BAT-EMC | Stops the scanner and measurement if the adjustment function returns false. | Bug | 3.19.1.8 |
| CHG0030508 | BAT-EMC | Add the commented graph in copy to clipboard. Adding the EUT and managing the selection of a single band or group of bands | Evolution | 3.19.1.8 |
| INC0012824 | BAT-EMC | Pulse width adjustment option is not retained when duplicating a test. The user has to check it again and select the method again. | Bug | 3.19.1.8 |
| INC0012783 | BAT-EMC | Wizard problem: do not measure between bands that have a Qpeak | Bug | 3.19.1.8 |
| CHG0030482 | BAT-EMC | PXE N9048B Keysight driver. | Evolution | 3.19.1.8 |
| INC0012763 | BAT-EMC | Add the DLL E4440A_LAN inside of the solution | Bug | 3.19.1.8 |
| INC0012788 | BAT-EMC | The Tektronix API32 does not allow to do under 100k span. | Bug | 3.19.1.8 |
| INC0012765 | BAT-EMC | Import problem of big projects | Bug | 3.19.1.8 |
| CHG0030505 | BAT-EMC | Change the limit to a test that already has results. We can now delete and add limits at the same time. Addition of an OK / Cancel question "Added limit (s) will be associated with existing Prescans, in the corresponding frequency bands" when adding limits | Evolution | 3.19.1.8 |
| INC0012253 | BAT-EMC | Add Labview extended exemple to setup | Bug | 3.19.1.9 |
| CHG0030565 | BAT-EMC | Manual Update. EMI by Band add tags and replace Prescan by Scan | Evolution | 3.19.1.9 |
| INC0013018 | BAT-EMC | Issue on test closure | Bug | 3.19.1.9 |
| CHG0030380 | BAT-EMI By Band | Several Improvements and Bug EMI by Band: Bug on dialogBox. Solution: we have to stop the execution before close the application. Be able to change the suspect's function after performing the tests. Renamed "Prescan" in "Scan". Incorrect report if test partially measures a limit. Finishing with sub-band directory templates. Added a Status in LimitBandReport and LimitBandResultReport. Rename the meas unit. time from ms / point to ms / step. | Evolution | 3.19.1.9 |

| | | | | |
|------------|----------|---|-----------|----------|
| | | Analytic reporting bug for copy or project import. Followup Case of the combo, Correction: ComboBox, when it is editable. Analytic reporting renaming. Analytic report: instead of started put in progress. Antenna factor does not apply for some antennas. VSTS 1371: Analytic Reporting: report on the max of the legend and adjust level polarizations, returns selectedPolarization = -1 in the Maximization H + V case. User Story 1377: EmiByBand FSP. Change the unit of measurement time for the FFT in ms. VSTS 1372: random error in the execution module. VSTS 1371: Analytic Reporting: report on the max of the legend and adjust level polarizations. VSTS 1370 adds chart by group for anatytic reporting. VSTS 1329 Maintenance 3.19.1.6 Duplicate a limit causes BAT-EMC to crash. AnalyticReporting: report crashes. Case selection analytic reporting. Initialization added in AnalyticReport.cs | | |
| INC0013001 | BAT-ELEC | Multiple reported issue from Bat-Elec. Minor scope change. Fix Autowave issues. Add VDS200Q. Add names to dictionary to avoid #name. Add PFS503N version. Start log with Elec | Bug | 3.19.1.9 |
| INC0013012 | BAT-EMC | RTM3004 Scope crashes when receiving settings | Bug | 3.19.1.9 |
| CHG0030564 | BAT-EMC | Add SetTimeout command in scripts to help control devices with no "endchar" | Evolution | 3.19.1.9 |
| INC0012952 | BAT-EMC | Fixed last point problem FFT Data Reduction in ESU | Bug | 3.19.1.9 |
| INC0012985 | BAT-EMC | Hide modulation for transfert function measurement with signal generator | Bug | 3.19.1.9 |
| INC0012986 | BAT-EMC | Shielding effectiveness in reveb: Crash when sub-range is displayed + correction View efficacy screen | Bug | 3.19.1.9 |
| INC0012972 | BAT-EMC | Manual mode max hold: crash while driving the turntable mast | Bug | 3.19.1.9 |
| INC0013006 | BAT-FT | ZNL6 not working with Bat-FT and ZNC driver. New beta driver added | Bug | 3.19.1.9 |
| CHG0030557 | BAT-ELEC | Add Driver for EmTest Compact NX5. Add Burst Alternate mode. Add Surge 1Ph/3Ph AC/DC. Add DipsDC, DipsAC, DropsDC, DropsAC, BurstDC | Evolution | 3.19.1.9 |
| INC0012991 | BAT-EMC | The export result generates data for all positions plus SVSWR. Fixed bug copy / paste and duplication. | Bug | 3.19.1.9 |
| INC0012993 | BAT-EMC | Report issue when using a post in the project | Bug | 3.19.1.9 |
| INC0013002 | BAT-EMC | Database error when creating 2nd equipment with same name | Bug | 3.19.1.9 |
| INC0012996 | BAT-EMC | LD200 No more working | Bug | 3.19.1.9 |
| INC0012995 | BAT-EMC | Remote not released with EMTest devices | Bug | 3.19.1.9 |
| INC0012997 | BAT-EMC | Add RDS200 as PF2 auxilliary power supply for PFS200N | Bug | 3.19.1.9 |
| INC0012998 | BAT-EMC | Add Single Dip pulse similar to Single Drop with PFS200 | Bug | 3.19.1.9 |
| INC0012761 | BAT-SCAN | BAT-SCAN did not work with multisweep | Bug | 3.19.1.9 |
| INC0012971 | BAT-EMC | Problem Prescan in infinite loop | Bug | 3.19.1.9 |
| INC0012906 | BAT-EMC | Reverb equipment Intialization strategy (CRBM) | Bug | 3.19.1.9 |

| | | | | |
|------------|-----------------|---|-----|-----------|
| INC0012980 | BAT-CLICK | Bat-Click crashes due to pilote3.dll unable to load log4cxx | Bug | 3.19.1.9 |
| INC0012820 | BAT-EMC | Added option to use 'u' instead of 'μ' (especially for Chinese PCs) | Bug | 3.19.1.9 |
| INC0012944 | BAT-EMC | Fills the database at the end of execution (CRBM calibration) | Bug | 3.19.1.9 |
| INC0012962 | BAT-EMC | Bosch specific database option. Create secure and insecure versions of PCAN tools | Bug | 3.19.1.9 |
| INC0012288 | BAT-EMC | Test report creation (header and footer) | Bug | 3.19.1.9 |
| CHG0030380 | BAT-EMI By Band | 1508 - Improved "SynthesByGroupUtil.GetSynthesByGroupList" Method - Reports can now be made on projects that have folders in folders (Recursive Management). // 1452 - Know if the test is running or not: add progress bar horizontal. // 1498 - Preamp test for the ESU. // 1499 - Add com simulation to debug real drivers in simulation. // 1500 - Added overload (INC0012964) made for ESW and ESU. // Add the Tag Number in the TestReport. // 1445 - Selection of test return limits. Homogeneity windows selection limits: blue and orange Nexio. OptionsReport: SelectedEmiByBandLimitList property = list of OptionsEmiByBandLimitReport. Adding TestTypeName in TestReport, Fixing Resources for TestType from TestReport, Enlarging Window Suspicious Edition in Execution. // 1442 - Modification of limits or suspects: the Results tab of the test is not updated. // 1346 - Improved limit selection for report generation, display only the available limits (instead of displaying all the project limits, you have to display the limits of the elements selects taking into account the hierarchy) to be able to select several limits, display the name, description of the limit with the folders and the type of test of each limit. // 1438 - Report generation bug. // 1391 - Uniformization of the enter / escape key. 1390 - Double Click on axes in the Result tab made BAT-EMC crash. Issue with limits selection on the report. | Bug | 3.19.1.10 |
| CHG0030380 | BAT-EMI By Band | Execution Module: 1472 - Followup reduce the size of the window and remove the third column. // 1464 - Data reduction style: set size 4 by default. // 1456 - Manual / additional measurement could not be started if there is a measurement in progress. // 1463 - Curves look blurry (anti aliasing) => finer by default (1 instead of 2). // 1460 - Show table => show suspects (show by default with 3). 1467 - For the cursors: Design buttons, textbox (seemed grayed out). 1469 - Manual measurement: put standard buttons. 1470 - Right-click in the execution module, incorrect font. 1455 - Rename "Manual measurement" to "Additional measurement". 1462 - Abs edit / ord edit: to remove or put a single "Axes Settings". 1501 - CommentedGraph, Remove 4 Tags Settings. Report template: Adding the Number tag at the TestReport | Bug | 3.19.1.10 |

| | | | | |
|------------|--------------------|--|-----------|-----------|
| CHG0030380 | BAT-EMI By Band | Wizard Definition Module: 1476 - Delete selected Prescan (add message confirmation), LimitBandFilter correction if Result without Frequency Range. 1475 - Qpeak limit with 1s measurement time, Average with 10ms measurement time, no Peak level, choose Peak instead of Qpeak. => Wizard by default in the case Peak instead of Qpeak the measurement time of the Peak must be that of the Average (and not 5ms by default). 1486 - Module definition, input protection to off if auto attenuation is off. 1504 - Added report templates in SVN + BAT-EMC setup. | Bug | 3.19.1.10 |
| INC0013093 | BAT-EMC | Driver TDEMI VISA Frequency Start <30Hz managed | Bug | 3.19.1.10 |
| INC0013038 | BAT-EMC | Monitoring Viewer - Diagrams have less information-density | Bug | 3.19.1.10 |
| INC0013036 | BAT-EMC | Monitoring Viewer - Remove/hide a curve | Bug | 3.19.1.10 |
| INC0013037 | BAT-EMC | Monitoring Viewer - Name of the diagrams | Bug | 3.19.1.10 |
| INC0012820 | BAT-EMC | Display error on 'μ' locate in Receiver setting | Bug | 3.19.1.10 |
| INC0013087 | BAT-EMC | License Manager, Reverb Ressources visible after selecting "Reverberation immunity". Power disturbance and Field disturbance appears. | Bug | 3.19.1.10 |
| INC0013035 | BAT-EMC | Monitoring Viewer - diagram size optimisation (additionnal row) | Bug | 3.19.1.10 |
| INC0013040 | BAT-EMC | Report Monitoring - Some EasyMon channels are unselected | Bug | 3.19.1.10 |
| INC0013084 | BAT-EMC | Disable PeakSearch function for ESI during manual maxhold | Bug | 3.19.1.10 |
| INC0013058 | BAT-EMC | Limitation on Sub Range frequencies on PeakSearch | Bug | 3.19.1.10 |
| CHG0030576 | BAT-EMC | Manual Update = (Update "limits band result tags") | Evolution | 3.19.1.10 |
| INC0013076 | BAT-EMC | Tag report for Reverb emission => English : "ReverbTestEMI" , "ReverbSREMI" , "ReverbEMICal" and French : "EssaiCRBMEMI" , "SBCRBMEMI" , "CalCRBMEMI" | Bug | 3.19.1.10 |
| INC0013074 | BAT-EMC | Settings in manual maxhold // issue in the PeakSearch | Bug | 3.19.1.10 |
| INC0013001 | BAT-EMC | Multiple reported issue from Bat-Elec. UCS500_B3 and M4 issue from 3.17 to 3.19. Bad merge results in longer Timeout. | Bug | 3.19.1.10 |
| INC0013004 | BAT-EMC | The linearityCheck tool crashes when there is a specified path in the configuration. | Bug | 3.19.1.10 |
| INC0013064 | BAT-EMC | Special Dwell Time frequency list doesn't get saved with test/project on publish | Bug | 3.19.1.10 |
| INC0013039 | BAT-EMC | Monitoring Report Window: no possibility to use the scrollbar with mouse wheel | Bug | 3.19.1.10 |
| INC0012920 | BAT-EMC | Driver E4440 (GPIB). Fix slow measurement with QP detector for finals | Bug | 3.19.1.10 |
| INC0012945 | BAT-EMC | Field probes and field meters are not filtered accordingly the setup for other position than 1 | Bug | 3.19.1.10 |
| INC0013042 | BAT-EMC | UCS500N5 error with Dips/Drops in new version. UCS500N5 not able to count pulses for Dips/Drops | Bug | 3.19.1.10 |
| INC0012288 | BAT-EMC | Test report creation (header and footer) | Bug | 3.19.1.10 |

| | | | | |
|------------|--------------------|--|-------------------|-----------|
| CHG0030380 | BAT-EMI By Band | <p>1355 - Driver modification EMI By Band for preamp. Issue on ESR. // 1403 - Filter problem in the tape display. // Change diagram of the report templates. // 1485 - Module check the adjust level. // 1458 - Conclusion of the test in ReadOnly and Automatic. // 1484 - In the result, it is necessary to display only the bands which are related to the Prescans of the test for each polarization. // In the "result" window do not put a horizontal limit for <30M. // 1483 - Peak detection rename in Spike detection. // 1468 - Remove Manual measurement preselected frequency range. // 1466 - Manual measurement when changing the setup, the choice of editing does not take into account the modified setup. // 1326 - Management of setup containing several types of antenna. // ValueTuple management regardless of the number of fields in Template 4: improvement. // Manage ValueTuple (2 fields) in Template 4. // 1454 - Design : the scrollbar of the scans does not follow the progress of the test. // 1465 - Design : When selecting a band, you can not see that the band is selected. // 1453 - View measurement settings at the top of the graph moment (meas. time, RBW, preampli ON/OFF, attenuation). Issue selection problem in the report.</p> | Bug/ Evolution | 3.19.1.11 |
| CHG0030380 | BAT-EMI By Band | <p>1481 - External equipment !: Add custom external, add tooltip (add a comment only). // 1489 - Add difficult folder: add element "radiated electric emission" without going through a test. // 1477 - Wizard : Remove the blue background and improve it. // 1474 - Wizard : reduce the header and footer to maximize the space given on the board. // 1473 - Wizard : the settings are more important than the setup (set to the left of the setup). // 1478 - Display Prescans => put label "Not Started, Finished, InProgress." // 1479 - Display Prescans => put 4 action buttons (toolbar).</p> | Evolution | 3.19.1.11 |
| INC0013056 | BAT-EMC | Using Easy Monitoring configuration is not possible (button test on BAT-EMC) | Bug | 3.19.1.11 |
| INC0012121 | BAT-EMC | Keithley 2000 error | Bug | 3.19.1.11 |
| CHG0030595 | BAT-EMC | Display an alert message when the "FFT" function is selected | Evolution | 3.19.1.11 |
| INC0013147 | BAT-EMC | VEE Tools are showing invalid pointer error | Bug | 3.19.1.11 |
| INC0013170 | BAT-EMC | Detector not visible on all subranges of subrange list for emissions for global procedure | Bug | 3.19.1.11 |
| INC0012962 | BAT-EMC | Options databases | Bug | 3.19.1.11 |
| INC0013163 | BAT-EMC | Monitoring - Changing the size of graph titles in reports | Evolution | 3.19.1.11 |
| INC0013158 | BAT-EMC | Showing ms/step instead of ms/pts in english version | Bug | 3.19.1.11 |
| INC0013131 | BAT-ELEC | ELEC - checking possible report tags leads to closure | Bug | 3.19.1.11 |
| INC0013115 | BAT-EMC | Driver TDEMI_VISA: correction of the blocking in receiver mode and FFT with several scans during a Prescan. | Bug | 3.19.1.11 |
| INC0013130 | BAT-EMC | Error message when using Export All menu (test without monitoring channel) | Bug | 3.19.1.11 |
| INC0013115 | BAT-EMC | TDEMI_VISA driver: addition of a scan stop at the end of the continuous measurement of peak search maxhold. Manual suspects not running properly. | Bug | 3.19.1.11 |

| | | | | |
|------------|-----------------|--|-----------|-----------|
| INC0013122 | BAT-EMC | Amplifier Calibration not working | Bug | 3.19.1.11 |
| INC0013119 | BAT-EMC | TDEMI Driver: Fixed bug when multiple detectors are chosen in GetMeasure. Increase accuracy for frequencies to avoid having the same between Freq Start and Freq Stop and activate the bargraph. Added colors to differentiate the detectors. | Bug | 3.19.1.11 |
| INC0013119 | BAT-EMC | Advanced Finals, PeakSearch. When you erase the markers, you can not add any more. "CALC: MARK: AOFF" command removed | Bug | 3.19.1.11 |
| INC0013119 | BAT-EMC | In the case of a simple Prescan with only one sweep, the setting of the "SwpCnt" parameter of the TDEMI was not done and remained set to the last one. | Bug | 3.19.1.11 |
| CHG0030380 | BAT-EMI by Band | 1524 - "Close" button inaccessible (depends on the resolution) // 1496 reports: Equipment used does not take into account the appendix. Warning: this will only work on new tests or tests for which we restart the treatments. // 1495 reports: In the report, you should not show bands that are not measured. Displays the bands present in the Prescans of the test (GetSynthesByGroupList). Fixed calculation of IsPass at SynthesByGroupUtil level (unclusive addition, Pass correction by default). // 1518 - Access violation exception to investigate. // 1511 - Unable to generate a report on an analytic reporting alone. Warning: the limit guideline of an Analytic Report is now stored in the Emi4_EssaiLimit table but for the old Analytic Report, it is necessary to modify and save so that the record is added to the table. | Bug | 3.19.1.12 |
| CHG0030620 | BAT-EMC | TDEMI : Management of FFT and FFT with data reduction (management of Multichannel/Traditionnal option in receiver mode) | Evolution | 3.19.1.12 |
| CHG0030619 | BAT-EMC | Driver R&SZND for SCP. | Evolution | 3.19.1.12 |
| INC0013292 | BAT-EMC | The software crash with a new subrange and a virtual receiver | Bug | 3.19.1.12 |
| CHG0030618 | BAT-EMC | Driver Robot Denso for BAT-SCAN | Evolution | 3.19.1.12 |
| INC0013194 | BAT-EMC | Automatic adjust level issue for bands with slopes. Problem with suspicious calculation max per band. Also problem about limits with decimal numbers. | Bug | 3.19.1.12 |
| INC0013288 | BAT-EMI by Band | Display problem per band group: See attached file | Bug | 3.19.1.12 |
| INC0013274 | BAT-EMI by Band | Wizard problem on the bands of limits covered by several setups | Bug | 3.19.1.12 |
| INC0013276 | BAT-EMC | Report problem per band group (case <30MHz in Horizontal or Vertical) | Bug | 3.19.1.12 |
| INC0013289 | BAT-EMC | HP E7400 driver: modification to use the classic AVG detector (not EMI) | Bug | 3.19.1.12 |
| INC0013240 | BAT-EMC | Problem discontinuity import curve max | Bug | 3.19.1.12 |
| INC0013243 | BAT-EMC | No longer automatically selects graphs with defaults when opening the Monitoring Report window. | Bug | 3.19.1.12 |
| INC0013238 | BAT-EMC | No Spurious Emission measurement in equipment setups | Bug | 3.19.1.12 |
| INC0013168 | BAT-EMC | Automatic validation of emissions sub range | Bug | 3.19.1.12 |
| CHG0030608 | BAT-ELEC | Add information about tag for BAT-ELEC version '<BR/VersionBAT>' and '<BR/Version>' | Bug | 3.19.1.12 |

| | | | | |
|------------|----------|---|-----------|-----------|
| INC0013112 | BAT-EMC | When two materials shared the same connection address, we create only one connection for both. This mechanism is implemented only on USB/Ethernet communication and NOT ieee. This way the LISN and TDEMI shares the same connection. | Bug | 3.19.1.12 |
| INC0013219 | BAT-EMC | Bug report graphs in .dotx | Bug | 3.19.1.12 |
| INC0013187 | BAT-EMC | Changed the check to find the full unbroken frequency band in the calibration if it matches the sub range of the test. (Reverb Immunity) | Bug | 3.19.1.12 |
| INC0013210 | BAT-EMC | Antenna Factor Error Message When Launching Final Advance | Bug | 3.19.1.12 |
| CHG0030399 | BAT-EMC | Reduced display time for transfer function and antenna factor | Evolution | 3.19.1.12 |
| INC0013093 | BAT-EMC | Driver TDEMI VISA Frequency Start <30Hz managed | Evolution | 3.19.1.12 |
| INC0012964 | BAT-EMC | 1503 : Overload Management for FSIQ (tested on Virtual Instrument v6.52) | Bug | 3.19.1.12 |
| CHG0030606 | BAT-EMC | Update Getting started Easy Monitoring = New visu Monitoring added | Evolution | 3.19.1.12 |
| CHG0030604 | BAT-EMC | Manual Update = Add test creation assistant improvement for setup with multiple antennas | Evolution | 3.19.1.12 |
| INC0013204 | BAT-EMC | Monitoring -- Unable to change min/max values of the axis in immunity tests after open the channels settings | Bug | 3.19.1.12 |
| INC0013054 | BAT-EMC | Monitoring issue, BAT-EMC crash if variable = null | Bug | 3.19.1.12 |
| INC0013186 | BAT-EMC | When configuring the regulation parameters of a Conducted Power Calibration subrange, if the admin password is cancelled then the system crashes. | Bug | 3.19.1.12 |
| INC0013196 | BAT-EMC | Issue with special characters exported + EMS_Calibrations table not exported during calibration export | Bug | 3.19.1.12 |
| INC0013063 | BAT-EMC | Taking into account the rotation time for Reverb EMI Calibration | Bug | 3.19.1.12 |
| INC0013357 | BAT-SCAN | Bug Scanner (scan speed drops sharply after a pause in NFS viewer) | Bug | 3.19.1.13 |
| INC0013356 | BAT-EMC | IMM driver bug that prevents NfsConf from closing | Bug | 3.19.1.13 |
| INC0013353 | BAT-EMC | Problem in parameter editing of a Scan and modification of a setup during project change | Bug | 3.19.1.13 |
| CHG0030618 | BAT-EMC | Driver Denso | Evolution | 3.19.1.13 |
| INC0013221 | BAT-EMC | Automatic Threshold Seek not functioning as expected in open loop (net power) | Bug | 3.19.1.13 |
| INC0013064 | BAT-EMC | Special Dwell Time frequency list doesn't get saved with test/project on publish | Bug | 3.19.1.13 |
| CHG0030480 | BAT-SCAN | Modification Driver BAT-Scanner | Evolution | 3.19.1.13 |
| CHG0030607 | BAT-EMC | Driver imp3D | Evolution | 3.19.1.13 |
| INC0013322 | BAT-EMC | Reverb test procedure titled as calibration | Bug | 3.19.1.13 |
| INC0013013 | BAT-EMC | Antenna emission was not taken into account (only antenna) | Bug | 3.19.1.13 |
| INC0013235 | BAT-EMC | The "Target" column has been renamed to "Calibration / Target" for EMS tests | Bug | 3.19.1.13 |
| INC0013309 | BAT-EMC | Do not re-run the finals in auto mode if done directly by data reduction | Bug | 3.19.1.13 |
| INC0013214 | BAT-EMC | Bug resolved on CWS500N1 | Bug | 3.19.1.13 |
| INC0013309 | BAT-EMC | CISPR25 3rd function modification for re-measurement QPeak | Bug | 3.19.1.13 |

| | | | | |
|------------|-----------------|--|-----------|-----------|
| INC0013297 | BAT-CLICK | Improvement of BAT Click to be able to launch a test of 2 hours with a measurement time of 500 micro seconds. | Bug | 3.19.1.14 |
| INC0013297 | BAT-CLICK | Improvement = Transformation "class" into "struct" for the points of measurement | Evolution | 3.19.1.14 |
| INC0013377 | BAT EMI by Band | Possibility to make a measurement with RBW of 10kHz with a 3dB filter. | Bug | 3.19.1.14 |
| INC0013383 | BAT EMI by Band | Adding a report template for "other test types" with no campaign project | Evolution | 3.19.1.14 |
| CHG0030380 | BAT EMI by Band | Fixed the display of markers and Dark style | Bug | 3.19.1.14 |
| INC0013379 | BAT EMI by Band | Issue when copying all tests of a test type+ Adding Logs | Bug | 3.19.1.14 |
| INC0013404 | BAT EMI by Band | Reverb BAT EMI fix for Calibration and Test | Bug | 3.19.1.14 |
| INC0013174 | BAT EMI by Band | Execution module crash | Bug | 3.19.1.14 |
| INC0013378 | BAT EMI by Band | Problem of viewing settings in the BAT EMI by Band module at runtime | Bug | 3.19.1.14 |
| INC0013375 | BAT EMI by Band | When duplicating a test, don't duplicate "execution date", "batversion" and "equipmentRessources". EmiByBand Update the run date only when launching a measurement | Bug | 3.19.1.14 |
| INC0013416 | BAT-EMC | In scripts, MESSAGE did not work anymore | Bug | 3.19.1.14 |
| INC0013409 | BAT-EMC | Banalisation of "" in the name of the materials | Bug | 3.19.1.14 |
| INC0013360 | BAT-EMC | Crash when previewing graph in the report window of the monitor due to.vmf with display mode in advanced while only one modulation is present | Bug | 3.19.1.14 |
| INC0013237 | BAT-EMC | Optimization to reduce execution time during multiple scans | Evolution | 3.19.1.14 |
| INC0013303 | BAT-EMC | Sweeptime correction for N9917A. Add driver Keysight FieldFox N9917A (VNA mode) | Bug | 3.19.1.14 |
| CHG0030607 | BAT-EMC | Driver imp3D correction bug connexion | Bug | 3.19.1.14 |
| INC0013380 | BAT-EMC | Problem corrected, the min and max frequency range is calculated according to the min and max frequencies of the scan of the procedure (for each polarization) | Bug | 3.19.1.14 |
| INC0013381 | BAT-EMC | Crash when reading result | Bug | 3.19.1.14 |
| INC0013331 | BAT-EMS | Crash on closing and not update 'run date'. Adding protection and deleting a RAZDEL + Adding logs | Bug | 3.19.1.14 |
| INC0013384 | BAT-EMC | New driver Agilent N9320B | Bug | 3.19.1.14 |
| CHG0030609 | BAT-EMC | Manage only the ascending scan | Evolution | 3.19.1.14 |
| INC0013214 | BAT-EMC | CWS500N1 latest fix | Bug | 3.19.1.14 |
| INC0013330 | BAT-EMC | Driver Agilent_N90XX: Add bands low and full for the preamplifier | Evolution | 3.19.1.14 |
| INC0013361 | BAT-EMC | Problem opening test "radiated electric immunity check" with subranges containing "circular" polarization | Bug | 3.19.1.14 |
| INC0011490 | BAT-EMC | Manual mode for the 1st frequency and 1st angle on all subranges except the first, the status remains in "not started". It must be "in progress". | Bug | 3.19.1.14 |
| INC0013457 | BAT-EMC | Analytic reporting was no longer displayed | Bug | 3.19.1.14 |
| INC0013453 | BAT-EMC | Issue with message "probe change for multisensor calibration" | Bug | 3.19.1.14 |

| | | | | |
|------------|-----------------|--|-----------|-----------|
| INC0013413 | BAT-EMC | Reverberation Immunity - No longer in the Stirrer's SetAngle for each frequency for "Frequency sweep for fixed angle" mode | Bug | 3.19.1.14 |
| INC0013521 | BAT-EMC | Decrease of the break time to accelerate the export | Bug | 3.19.1.15 |
| INC0011008 | BAT-EMC | Added possibility to change the name of a "final" function when importing into another test | Bug | 3.19.1.15 |
| CHG0030661 | BAT-EMC | Multi-sensors calibrations by rows | Evolution | 3.19.1.15 |
| INC0013441 | BAT-EMC | Added protection to avoid an error message for reading an empty CADOSet. | Bug | 3.19.1.15 |
| CHG0030618 | BAT-SCAN | Addition of the ClearError function, offset of the origin | Evolution | 3.19.1.15 |
| INC0013539 | BAT-EMC | Correction EventUnload with Labview tools | Bug | 3.19.1.15 |
| INC0013478 | BAT-EMC | Advanced suspects make BAT-EMC crash when trying to add or update with empty Discrete frequencies for "Import frequency list" option | Bug | 3.19.1.15 |
| CHG0030480 | BAT-SCAN | Modification Driver BAT-Scanner | Evolution | 3.19.1.15 |
| INC0013535 | BAT-EMC | Activate the Reverb in the database | Bug | 3.19.1.15 |
| INC0013492 | BAT-EMC | Transfer function, export results = No longer put all the results on the same line in the Excel file. | Bug | 3.19.1.15 |
| INC0013524 | BAT-EMC | TDEMI_Visa mesure max hold multi detectors ne marchait pas | Bug | 3.19.1.15 |
| INC0013496 | BAT-EMC | Uniform MP Zone Calibration = Excel file generation, last paragraph concern, everything is on the same line | Bug | 3.19.1.15 |
| INC0013500 | BAT-EMI By Band | 1665 - Receiver R&S ESW: It is not possible to deactivate the input protection (10 dB). When Attenuation Auto was checked, Input Protection was also checked, even if the user was trying to change the value. Now, when Attenuation Auto is checked, Input Protection can be independently checked or unchecked. | Bug | 3.19.1.15 |
| CHG0030380 | BAT-EMI By Band | 1656 - Wizard issue. Correction inconsistent seizure of frequency step in the limit | Bug | 3.19.1.15 |
| CHG0030380 | BAT-EMI By Band | 1663 - Generation report takes a lot of time | Bug | 3.19.1.15 |
| CHG0030380 | BAT-EMI By Band | Scripts issues | Bug | 3.19.1.15 |
| CHG0030380 | BAT-EMI By Band | You can only run one test at the same time | Bug | 3.19.1.15 |
| CHG0030380 | BAT-EMI By Band | 1652 - Marker problem in a band group display. Markers may appear on imported tests | Bug | 3.19.1.15 |
| CHG0030380 | BAT-EMI By Band | 1653 - analytc reporting was no longer open | Bug | 3.19.1.15 |
| INC0013473 | BAT-EMC | When the box "Ask for equipment at Each sub-range" is ticked, when the software executes the final script made only to build a table, the diagram appears for each frequency. | Bug | 3.19.1.15 |
| INC0013486 | BAT-EMC | Closes Excel after generating a graph. Resolution causes a slight loss of time | Bug | 3.19.1.15 |
| CHG0030625 | BAT-EMC | Add low limit, high limit and generator level to available channels | Evolution | 3.19.1.15 |
| INC0013455 | BAT-EMC | Synchronisation error of UCS is not reported to the user | Bug | 3.19.1.15 |

| | | | | |
|------------|--------------------|---|-----------|-----------|
| INC0013112 | BAT-EMC | When two materials shared the same connection address. In order to control the LISN of the TDEMI, we create two materials in BAT-EMC : one for the LISN and one for the TDEMI. in the connection, we set up the same connection address. In BAT-EMC (for ethernet only), if two materials share the same address, internally, BAT-EMC creates only one connection so both LISN and TDEMI use the same connection to send commands. | Bug | 3.19.1.15 |
| INC0013477 | BAT-VISU | Crash BAT-VISU when transferring suspect to final table and do it again | Bug | 3.19.1.15 |
| INC0013466 | BAT-EMC | Driver N9340B: add to setup and creation of the user interface | Evolution | 3.19.1.15 |
| INC0013310 | BAT-EMC | Tool Lecroy_DSO_EMS: manage USB communication | Bug | 3.19.1.15 |
| INC0013428 | BAT-EMC | Limit RF2 Filter ON / OFF added in ESW receiver settings. | Evolution | 3.19.1.15 |
| INC0013476 | BAT-EMC | Crash BAT when selecting limit and then cancel. Problème pointeur mal réinitialisé. | Bug | 3.19.1.15 |
| INC0012539 | BAT-EMC | Monitoring add a new option to allow to save as an image to format .jpeg or .png or .emf. | Evolution | 3.19.1.15 |
| INC0013453 | BAT-EMC | Issue with message Probe change for multisensor calibration | Bug | 3.19.1.15 |
| CHG0030666 | BAT-EMC | Add new calculation mode for Uniform Field Calibration : ISO 11451-2. Fixing error percentage calculation report | Bug | 3.19.1.16 |
| INC0013583 | BAT-EMC | Manual mode during Uniform field calibration issue when restart automatic mode | Bug | 3.19.1.16 |
| INC0013616 | BAT-EMC | Activation of Wattmeters and power probes for the the chain measurement of current immunity conducted in voltage | Bug | 3.19.1.16 |
| INC0012042 | BAT-EMC | Rework of Tecknic ClearPath stirrer driver. Correction of the initialization | Bug | 3.19.1.16 |
| INC0013282 | BAT-EMC | Add the CISPR and MIL Filter 6dB/3dB for the ESR | Evolution | 3.19.1.16 |
| CHG0030661 | BAT-EMC | Optimization request "verification of multi-point calibration uniform zone" valid | Bug | 3.19.1.16 |
| INC0013597 | BAT-EMC | Addition of two drivers: one that controls the mast and the other the turntable | Evolution | 3.19.1.16 |
| INC0013001 | BAT-ELEC | Multiple reported issue from Bat-Elec | Bug | 3.19.1.16 |
| INC0013570 | BAT-EMC | TDEMI RF input selection | Bug | 3.19.1.16 |
| INC0013607 | BAT-EMC | Problem when special characters in files are read in unicode by CStdioFile class | Bug | 3.19.1.16 |
| CHG0030482 | BAT-EMI By Band | Addition of the "Accelerated TDS" functionality (in FFT mode). Bug fix (the test ended before the receiver sweep ended, the data was misinterpreted due to BigIndian / LittleIndian) | Bug | 3.19.1.16 |
| INC0013484 | BAT-EMC | FSV and FSU scan problem | Bug | 3.19.1.16 |
| INC0013214 | BAT-EMC | CWS500N1 Serial+GPIB | Bug | 3.19.1.16 |
| CHG0030664 | BAT-EMC | Manual Update = Update screenshot and details from page 15 to 22 | Evolution | 3.19.1.16 |
| INC0013591 | BAT-EMC | Driver ESW: Limiter ON/OFF is set before coupling and attenuator | Bug | 3.19.1.16 |
| INC0012488 | BAT-EMC | Problem with report generator. The order of the results in the SQL query has an incidence which must be taken into account | Bug | 3.19.1.16 |

| | | | | |
|------------|--------------------|--|-----------|-----------|
| INC0013060 | BAT-EMC | Reverberation stirrer is now visible by default. Renaming in "License manager" of modules on the revert starting with "Reverberation" in English and "CRBM ..." in French | Bug | 3.19.1.16 |
| INC0013166 | BAT-EMS | Addition of a decimal for the target in BAT-EMS if greater than 100. Addition of the dBpT unit for the magnetic field calibrations | Evolution | 3.19.1.16 |
| INC0013594 | BAT-EMC | Problem with the update following CHG0030661 for DllFrancais.rc | Bug | 3.19.1.16 |
| INC0013563 | BAT-EMC | Return the "Data version" field to the "About BAT-EMC" | Bug | 3.19.1.16 |
| INC0013576 | BAT-EMC | Large project data, such as hundreds of test cases, cannot be deleted. | Bug | 3.19.1.16 |
| INC0013515 | BAT-EMC | Adding indexes to the database to speed up deletion | Evolution | 3.19.1.16 |
| CHG0030380 | BAT-EMI By Band | 1660 - Analytic reporting - Crash "copy to clipboard" | Bug | 3.19.1.16 |
| CHG0030606 | BAT-EMC | Addition of new monitoring for multi-point calibration | Bug | 3.19.1.16 |
| INC0012820 | BAT-EMC | DLL loading problem following modification 'μ' | Bug | 3.19.1.16 |
| INC0013554 | BAT-SCAN | Display of pop up of the DLL of the network analyzer used during the tests in vector | Bug | 3.19.1.16 |
| INC0013477 | BAT-EMC | When we transfer to the finals, we remove from the table of suspects | Bug | 3.19.1.17 |
| INC0013597 | BAT-EMC | INNCO adding max height 3.9m | Bug | 3.19.1.17 |
| INC0013643 | BAT-EMC | Correction of copy / paste error INC0013166 ticket | Bug | 3.19.1.17 |
| INC0013626 | BAT-ELEC | Electrical test mode 3 did not work, mode 1 work fine. Error if user change manually waveform on device | Bug | 3.19.1.17 |
| INC0013597 | BAT-EMC | Delete unnecessary projects. Correction Set polar and Reference. New projects using innco32.dll (new signatures and prototypes of functions). The innco32.dll has been renamed manually. Addition: the reference starts again if it fails. Addition of two drivers, one that controls the mast and the other the turntable | Bug | 3.19.1.17 |
| CHG0030669 | BAT-EMC | Manual Update = Add Annex for sensitivity radio tests | Evolution | 3.19.1.17 |
| INC0013624 | BAT-EMC | Report Monitoring - The list of modulations in the report part is that of the test. | Bug | 3.19.1.17 |
| CHG0030618 | BAT-EMC | Correction of the clear error and taking into account of the standby error | Bug | 3.19.1.17 |
| CHG0030666 | BAT-EMC | Add new calculation mode for Uniform Field Calibration : ISO 11451-2. Blocking this method for the following configuration => 3 Columns, 1 Row. It works also with "By Row" option for the multisensor. Report modified for this method. Fixing InitStatus + WriteReport | Evolution | 3.19.1.18 |
| INC0013632 | BAT-EMC | ESW Driver: Sweep Time setting for scanning in IF mode (addition of Log) | Bug | 3.19.1.18 |
| INC0013001 | BAT-ELEC | Multiple reported issue from Bat-Elec | Bug | 3.19.1.18 |
| INC0013631 | BAT-EMC | Problem displaying value in finals if greater than 10GHz | Bug | 3.19.1.18 |
| CHG0030688 | BAT-EMC | Manual Update = Add MIL-STD-461 description for Reverb test. Explanation of theoretical calculation for Radiated Electric Immunity and Radiated Magnetic Immunity. Add details about offset calculation for Closed loop method with power limitation | Evolution | 3.19.1.19 |
| INC0013636 | BAT-EMC | Test setups with Easy monitoring configuration is facing with a 'System resource exceed' problem = Correction memory leak on Monitoring | Bug | 3.19.1.19 |

| | | | | |
|------------|--------------------|---|-----------|-----------|
| CHG0030380 | BAT-EMI By Band | 1804 - Performance display of a test. Optimization of the loading of the antenna list of a setup list. | Evolution | 3.19.1.19 |
| CHG0030380 | BAT-EMI By Band | 1805 - Image in "Commented Graph" does not appear well in the report. Switching to EMF instead of SVG | Bug | 3.19.1.19 |
| CHG0030380 | BAT-EMI By Band | 1807 - Allow sorting in the scan list | Evolution | 3.19.1.19 |
| CHG0030380 | BAT-EMI By Band | 1794 - Change of group causes the execution module to crash | Bug | 3.19.1.19 |
| CHG0030380 | BAT-EMI By Band | 1803 - Report by band group was not good | Bug | 3.19.1.19 |
| CHG0030380 | BAT-EMI By Band | MXE: Edition of the driver manager for the EMI drivers of the MXE. Input management, time delay so that the settings are set well | Evolution | 3.19.1.19 |
| CHG0030380 | BAT-EMI By Band | ESW driver: we adjust the inputs before the frequencies | Evolution | 3.19.1.19 |
| CHG0030380 | BAT-EMI By Band | 1762 - Add Limit ESW | Evolution | 3.19.1.19 |
| CHG0030380 | BAT-EMI By Band | 1761 - TestMesures \ EmiByBand. Replacement of linq with for loops in execution. Unit error when coming to set an offset for automatic re-measurement. Correction Db in dB. 2 - BAT-EMI by Band crashed when changing the display during measurement. | Bug | 3.19.1.19 |
| CHG0030687 | BAT-EMC | Add MIL STD method for Reverb (E-Field and Receive Antenna methods). | Evolution | 3.19.1.19 |
| INC0013669 | BAT-ELEC | Freeze when using manual coupler and close check window | Bug | 3.19.1.19 |
| INC0013558 | BAT-EMC | During reverb test, the software displayed message "moving turntable" instead of "moving stirrer" | Bug | 3.19.1.19 |
| INC0013728 | BAT-EMI By Band | Export = Adding order by frequency | Evolution | 3.19.1.19 |
| INC0013676 | BAT-EMC | LD 200 N driver error with pulse 5b | Bug | 3.19.1.19 |
| CHG0030685 | BAT-EMC | Modification of the link for TeamViewer | Evolution | 3.19.1.19 |
| CHG0030684 | BAT-EMC | Addition of new ETH CAN V2 scanner driver | Evolution | 3.19.1.19 |
| INC0013404 | BAT-EMC | Issues with reverb emissions = The reverb emissions calibration did not do a full rotation of the stirrer before ending the calibration | Bug | 3.19.1.19 |
| INC0013310 | BAT-EMC | Driver Lecroy_DSO_EMS: Add close AND init FUNCTION TO BE USED IN Initialize and Terminate script in order to avoid doing initialisation for each SEND and QUERY - Add logs as info | Bug | 3.19.1.19 |
| CHG0030618 | BAT-EMC | Denso Robot: added decoding of error codes. Homing correction, error management | Bug | 3.19.1.19 |
| CHG0030677 | BAT-SCAN EMS | Added Get Position function | Evolution | 3.19.1.19 |
| INC0013719 | BAT-EMC | Driver MXE and PXE : add configuration sweep time in ms for analyser mode. Agilent X-Series EMI Receiver Mode - Agilent N90XX MXE EMI - Agilent N90XX - Agilent N9048B PXE | Bug | 3.19.1.19 |
| INC0013626 | BAT-ELEC | Electrical test mode 3 did not work, mode 1 work fine. Change "Va" to "Vattl" to avoid replacing alternator voltage on other tests | Bug | 3.19.1.19 |
| INC0013647 | BAT-ELEC | ISO Pulse 1 is not working with CAR-Tester driver | Bug | 3.19.1.19 |
| INC0013709 | BAT-EMC | Bat-Emc shortcut is not properly set up after installation | Bug | 3.19.1.19 |

| | | | | |
|------------|-----------------|---|-----------|-----------|
| INC0013661 | BAT-EMC | Problem with request for "export all" for several modulations and without monitoring | Bug | 3.19.1.19 |
| INC0013597 | BAT-EMC | INNCO Mat / Turntable: removal of height limitation | Bug | 3.19.1.19 |
| INC0013685 | BAT-EMC | Add the Suspect list in Reverb Emission Test | Evolution | 3.19.1.19 |
| INC0013649 | BAT-EMC | Modification = during the report, the <BR/ApplicationTime> tag takes the time of the sub-range during a test with monitoring instead of that of the test + correction of the 'Back' button for the 3rd window of EASY Tool settings | Bug | 3.19.1.19 |
| CHG0030625 | BAT-EMC | Change low/high limit on display | Evolution | 3.19.1.19 |
| INC0013680 | BAT-EMC | The 'Add' function in external equipment used works again + possibility of adding a comment for the materials used | Bug | 3.19.1.19 |
| INC0013591 | BAT-EMC | ESW Driver: Change order of commands to properly manage coupling and attenuator with limiter. Display of a message to the user if the receiver changes the settings following an incorrect combination of settings | Evolution | 3.19.1.19 |
| INC0013682 | BAT-EMC | The "Set frequency" and "Finish" scripts of the field meter were not executed for CRBM calibrations | Bug | 3.19.1.19 |
| INC0012042 | BAT-EMC | Rework of Tecknic ClearPath stirrer driver. GetValue was missing | Bug | 3.19.1.19 |
| CHG0030674 | BAT-EMC | Manual Update = Explanation of READ for field probes + Addition of information on appendix 13 on transfer functions | Evolution | 3.19.1.19 |
| INC0013665 | BAT-SCAN EMS | Scanner speed too high | Bug | 3.19.1.19 |
| INC0013621 | BAT-EMC | During an emission test in analyzer mode on the FSU, the number of points could not be modified. Now we can use the FSU with 30001 points. | Bug | 3.19.1.19 |
| INC0013631 | BAT-EMC | Agilent X-Series EMI Receiver Mode Driver: Deactivation of marker frequency adjustment to central frequency to avoid error with the marker Meter (after PeakSearch MaxHold) | Bug | 3.19.1.19 |
| INC0013233 | BAT-EMC | Added possibility to lock / unlock the self-adjustment of the Y scale in BAT-EMS | Evolution | 3.19.1.20 |
| INC0013839 | BAT-ELEC | Easy monitoring tools not called when test is run | Bug | 3.19.1.20 |
| CHG0030380 | BAT-EMI By Band | 1948 - 3.19.1.x BAT-EMI by Band test publication did not export the test conclusion | Bug | 3.19.1.20 |
| CHG0030380 | BAT-EMI By Band | 1797 - Change the way of writing in the .emi4 file, Correction reading of result files (backslash issue) | Bug | 3.19.1.20 |
| CHG0030684 | BAT-SCAN | Preparation of the scanner driver | Evolution | 3.19.1.20 |
| INC0013891 | BAT-EMC | The data sent by the N9340B are always dBm. Conversion from dBuv to dBm is needed. | Bug | 3.19.1.20 |
| INC0013897 | BAT-EMC | Activate the chain to measure frequency disturbance in reverb | Bug | 3.19.1.20 |
| INC0013802 | BAT-EMC | Modification of the term "Open loop" (according to standard) by "Open loop or substitution" | Evolution | 3.19.1.20 |
| INC0013873 | BAT-EMC | Addition for a reverb test: the pulse width adjustment options for "PM ext" - Modify width of some lists. | Evolution | 3.19.1.20 |
| INC0013557 | BAT-EMC | Correction of incorrect value display in the info toolbar for reverb test | Bug | 3.19.1.20 |

| | | | | |
|------------|--------------------|---|-----------|-----------|
| INC0013821 | BAT-EMC | Add a message to avoid crash if the chain of the selected setup is empty. Modification name of the curve "Power level" by "Calculated field from average received power level" and addition of curve "Average received power" and "Max received power " | Evolution | 3.19.1.20 |
| INC0013818 | BAT-EMC | Correction of report tags for antenna reverb and e-field calibration | Bug | 3.19.1.20 |
| INC0013887 | BAT-EMC | Correction of Unit selection in receiver setting | Bug | 3.19.1.20 |
| CHG0030712 | BAT-EMC | Add channel 4 for OscLecroy (monitoring) | Evolution | 3.19.1.20 |
| INC0013695 | BAT-EMC | Modification of unusual sequence of commands (SET MOD, SET FREQ, SET LEVEL and not as expected SET FREQ, SET....) | Bug | 3.19.1.20 |
| CHG0030532 | BAT-EMC | Bug 1870: Report on BAT-FT HVLV Coupling Attenuation VNA | Bug | 3.19.1.20 |
| INC0013597 | BAT-EMC | Innco passage sur la DLL 32 bits d'Innco, si erreur de communication on fait un DisconnectMast (ou DisconnectTurntable) | Bug | 3.19.1.20 |
| INC0013871 | BAT-EMI By Band | Add LimitUnit in the report | Bug | 3.19.1.20 |
| INC0013854 | BAT-EMC | Issue connexion database after closing EMI or EMS, if export done by BAT-EMC | Bug | 3.19.1.20 |
| INC0013834 | BAT-EMC | Conducted Power Calibration available for Conducted Current Immunity test. | Bug | 3.19.1.20 |
| INC0013841 | BAT-EMC | DLL RSA306B (for script): Add two functions for users, SETRBW and SETREFLEVEL. SETRBW : 1 parameter, frequency in MHz. SETREFLEVEL: 1 parameter, Reference level in dBm | Evolution | 3.19.1.20 |
| INC0013777 | BAT-EMC | Wrong values in Easy Monitoring measurement : Probleme with Continuous VSWR measurement during test Option | Bug | 3.19.1.20 |
| CHG0030700 | BAT-EMC | Manual Update = Add Annex about NSA & SVSWR | Evolution | 3.19.1.20 |
| INC0013830 | BAT-EMC | Add possibility to choose a Conducted Power Calibration if it is in the project in a Conducted Voltage test | Bug | 3.19.1.20 |
| CHG0030699 | BAT-EMC | BAT-EMC in French, change name "ANE" to "NSA" | Evolution | 3.19.1.20 |
| INC0013720 | BAT-ELEC | CI 250 needs increased sampling rate | Bug | 3.19.1.20 |
| INC0013780 | BAT-EMC | Modification of the term 'Execute' to 'Activate'. Add an option for some equipments to launch the execution of the script "Initialize" at each execution | Bug | 3.19.1.20 |
| CHG0030694 | BAT-EMC | Manual Update = Add Annex 18 about Metrology | Evolution | 3.19.1.20 |
| INC0013740 | BAT-EMC | Remove space before paste from copy / paste graphs in reports | Bug | 3.19.1.20 |
| CHG0030532 | BAT-EMC | Report of a bug fix found during the implementation of Aspose graphs on the trunk | Bug | 3.19.1.20 |
| INC0013775 | BAT-EMC | Reversal NB / BB when displayed in the Advanced suspects window | Bug | 3.19.1.20 |
| INC0013731 | BAT-EMC | Addition of request to remove possible duplicates in the g_LabelObjets table after import (CATDBObject :: DBCorrigerApresImport () method) | Bug | 3.19.1.20 |
| INC0013624 | BAT-EMC | Report Monitoring -- problem when we add a new tag and press preview, visu monitoring crashed. | Bug | 3.19.1.20 |
| INC0012705 | BAT-EMC | FSE Driver add the 6dB and 3dB | Bug | 3.19.1.20 |

| | | | | |
|------------|----------|---|-----------|-----------|
| INC0013774 | BAT-EMC | Issue with display of NB / BB units for conducted current emissions - Correction of BL unit taken if no limit selected + Add protection on a pointer | Bug | 3.19.1.20 |
| INC0013310 | BAT-EMC | Driver Lecroy_DSO_EMS: Put back Init and close for SEND and QUERY function | Bug | 3.19.1.20 |
| INC0013773 | BAT-EMC | Export graph monitoring problem in .JPG and .PNG. Difference with metafile if several graphs | Bug | 3.19.1.20 |
| INC0014005 | BAT-EMC | Sending the command with start of Write \ 02 and end of write \ 03 | Bug | 3.19.1.21 |
| INC0014061 | BAT-EMC | Fix the case of objects that cannot be loaded because their idObject is lower than that of their parent | Bug | 3.19.1.21 |
| INC0014050 | BAT-EMC | Problem with the type of fields in g_LabelObjets following the modification to the ticket INC0013731 | Bug | 3.19.1.21 |
| INC0013581 | BAT-EMC | Issues with lines are highlighted in the equipment script editor (only in release) | Bug | 3.19.1.21 |
| CHG0030748 | BAT-EMC | User manual update (EN) | Evolution | 3.19.1.21 |
| INC0014007 | BAT-EMC | Comparaison of plots issue | Bug | 3.19.1.21 |
| INC0013542 | BAT-EMC | Problem if you generate an analytical reporting report by selecting it directly | Bug | 3.19.1.21 |
| INC0013838 | BAT-EMC | Correction issue followup | Bug | 3.19.1.21 |
| INC0014016 | BAT-EMC | Add the Active X library file in the solution libad-actx-4.6.528.exe | Bug | 3.19.1.21 |
| INC0014008 | BAT-EMS | We no longer resize the Y scale if the test is in status Completed at the opening of BAT-EMS + | Bug | 3.19.1.21 |
| INC0013886 | BAT-EMC | Auto Validation setups (Options/Driver) doesn't work in automatic mode | Bug | 3.19.1.21 |
| INC0013310 | BAT-EMC | Driver Lecroy_DSO_EMS: make connection only once | Bug | 3.19.1.21 |
| INC0013460 | BAT-EMC | Time at runtime is not correct for radio sensitivity testing | Bug | 3.19.1.21 |
| INC0013949 | BAT-EMC | Manage VI_ATTR_TERMCHAR_EN et VI_ATTR_SUPPRESS_END_EN | Bug | 3.19.1.21 |
| INC0013820 | BAT-EMC | Add possibility to choose the format of the exported files (.txt or .xls) when exporting the results of a test folder + Modification of the style of the window for selecting a folder so that it no longer uses the XP style | Bug | 3.19.1.21 |
| INC0013995 | BAT-EMC | Change "EN 61000-4-3/A1:2002" to "EN 61000-4-3:2006" | Bug | 3.19.1.21 |
| INC0013970 | BAT-EMC | Driver problem the command is correct but for this equipment (MSO54) you must put the complet command and not the short one : MEAS:IMM:TYPE FREQ is not working MEASUREMENT:IMMED:TYPE FREQUENCY Works!!! | Bug | 3.19.1.21 |
| INC0013985 | BAT-EMC | For conducted voltage immunity displays the 'current' tab in BAT-EMS only if 'Disturbance Measure' is checked in a sub-range | Bug | 3.19.1.21 |
| INC0013873 | BAT-EMC | Taking into account of PM ext in EMS in reverb | Bug | 3.19.1.21 |
| INC0013884 | BAT-EMC | Last freq made twice in certain cases (FFT), modification of the comparison | Bug | 3.19.1.21 |
| INC0013915 | BAT-ELEC | Bat-Elec is not sending informations to control tool | Bug | 3.19.1.21 |

| | | | | |
|------------|--------------------|---|-----------|-----------|
| INC0013839 | BAT-EMC | Labview tools are crashing | Bug | 3.19.1.21 |
| INC0013976 | BAT-EMC | Problem with export result for NSA Measurement | Bug | 3.19.1.21 |
| INC0013828 | BAT-EMC | Add in the context menu the possibility to export the monitoring data from a calibration + Add date column to the export result a calibration | Bug | 3.19.1.21 |
| INC0013948 | BAT-EMC | Problem with Equipment setup in the referential when you update the new equipment setup version from the referential he asks you again all the time + Problem with version 0 | Bug | 3.19.1.21 |
| INC0013950 | BAT-EMC | Fill in the fields "Executed with Version", "Equipment Resource Version" and "Limits Resource Version" for BAT-Click | Bug | 3.19.1.21 |
| INC0013950 | BAT-EMC | Click not opening due to missing log4net DLL. | Bug | 3.19.1.21 |
| INC0013943 | BAT-ELEC | Bat-Elec sets output off on arbitray waveform generator during init | Bug | 3.19.1.21 |
| INC0014117 | BAT-EMC | EOS char was staying in the buffer and shifted all read commands (tested on PXE) | Bug | 3.19.1.22 |
| INC0013834 | BAT-EMC | Case conversion problem Test conducted current with setpoint in conducted power | Bug | 3.19.1.22 |
| INC0014104 | BAT-EMI By Band | Radiated Electric with Automotive Bands Report Template = Addition of the name of the polarization above the graphs | Evolution | 3.19.1.22 |
| CHG0030684 | BAT-EMC | Driver Scanner ETH_CAN : speed management correction | Bug | 3.19.1.22 |
| INC0014045 | BAT-EMC | Issue with report tag "RegulParam" | Bug | 3.19.1.22 |
| INC0013853 | BAT-EMC | Crash Bat-visu3 | Bug | 3.19.1.22 |
| INC0014079 | BAT-EMC | Display problem following INC0013581 Many lines are highlighted in the equipment script editor | Bug | 3.19.1.22 |
| INC0013647 | BAT-ELEC | Standard 7637-3 added to Bat-Elec | Evolution | 3.19.1.22 |
| INC0014063 | BAT-EMC | Correction of infinite loop in reverb when the option "Multiple modulations / Successive application" is checked (Procedure tab in sub-bands) | Bug | 3.19.1.22 |
| INC0014054 | BAT-EMC | We do not read correctly the number of data of the Spectrum analyzer | Bug | 3.19.1.22 |
| INC0014065 | BAT-EMC | Problem with auto scale Y for viewing from hardware BAT-EMC | Bug | 3.19.1.22 |
| CHG0030532 | BAT-EMC | User Story 2094 = Create report template for setup Scope Metrology Template and NSA Report. Adding Metrology VNA template User Story 2094 = Create report template for setup Add immunity template FT VNA ETSI + FT Synthesizer for material report Delete old report template in the setup Equipment list report | Evolution | 3.20.0.0 |
| CHG0030532 | BAT-ELEC | User Story 2094 = BAT-ELEC report: Add transient BAT-ELEC IEC + ISO report | Evolution | 3.20.0.0 |
| INC0014054 | BAT-EMC | We do not read correctly the number of data of the SA | Bug | 3.20.0.0 |
| CHG0030533 | VISU V4 | Bug 2123: Deal with Font (Black or White only depending on Dark Mode). | Bug | 3.20.0.0 |

Added DarkMode Toggle in the toolbar of the chart
Changed icon of the Suspect/Final expander (to make them more look like expander).
Bug 2100: Integrate the information from the "Advanced Prescan" window into Visu.
WIP: Integration of a DialogProvider in FunctionDLL in order to be able to replace the MFC / WPF dialogs.
Bug 2127: Blinking mouse cursor (removed all CWaitCursor in Receivers Drivers).
Bug 2048: Display the speed of positioners during auto-execution.
Bug on click: Pass/Fail for the test
Bug 2126: Validation of the entry with the enter key
Modification at the framework level (go to the next field with entry).
For checkboxes, remember to use Alignment = Left
Bug 2118: Manual point on an empty Prescan.
Bug 2117: Buttons to go to MaxAngle & MaxHeight
Removed the stop button of Init Pos to a layer when we move the positioners from the Manual Point with a unique "Stop" Button.
Bug 2097: Visu V4: Add the conclusion (pass / fail) at the level of the Test List.
Bug 2116: Manual point comments not reset for a second point.
Bug 2114: Cursors lose options. Cursor positioned by default on the external curves. We replace the double click with a back to front search.
Bug 2108 = Bug with setup for Manual Point.
Bug 2107: Message in position during execution
Editing debug messages for reference issues
Cropping of the current angle in the control of the plate.
Bug 2104 = Adding Finish (-2) to free the memory without saving the results for report generation
Bug 2087: Default view. Modification of the layout.
Bug 2091: "Go to max position" hidden after running Prescan while setup is connected
Bug 2086: Position displayed at 0 with manual suspect + simple Prescan + H / V position. H / V display in visuV4. Displays H / V in Automatic and Manual operation
Hides polarization in Manual Point.
Bug 2084: Export Emi3 test impossible
Bug 1985: Graph settings. Tests the Prescan for results before displaying it.
Confusion over the selection of cursors / markers. Give priority to cursors.
Bug 2083: Legend takes up too much space when there are a lot of curves. Addition of a scrollviewer of ~ 4 lines.
Bug 2128: Manual point and default measurement time (in maximization mode). 1- If the sweep time of the sub-range is in ms / MHz or ms (we are supposed to be in analyzer mode) => MeasTime = 10ms. 2- If sweep time = auto then => MeasTime = 10ms. 3- If the sweep time is in ms / step (receiver mode), this value is used for the MeasTime.

| | | | | |
|------------|-----------------|--|-----|----------|
| CHG0030532 | BAT-EMC | Extended report = Deleting an empty source Correction: The Analytic reports were no longer published. Bug 2124 = Report with self-generated table (as BAT-ELEC): ability to repeat the table header on the following pages + missing SubTemplate_FT_Impedance_Measurement.dotx template. Renamed template. Fixed unloading of too many BatData. obsolete eutName EUTName and EUTFollowUp obsolete for backward compatibility Problem with finals that did not appear in reports (loop on suspects). Correction Edition Report on equipment in the wrong language. Bug 2090: Word settings plugin Bug 2069: Emission tag report. Bug 2135: Simpler final tag migration. Suspect and final tag with no title line available. User Story 2133: Report: SVSWR tests. Adding class SVSWR first part. User Story 1433: Tags. Graphs no longer return a stream but the path of a temporary file. User Story 1433: Tags. Add main tags for click rate test | Bug | 3.20.0.0 |
| INC0013970 | BAT-EMC | Driver problem the command is correct but for this equipment (MSO54) you must put the complete command and not the short one: MEAS:IMM:TYPE FREQ is not working MEASUREMENT:IMMED:TYPE FREQUENCY Works | Bug | 3.20.0.0 |
| CHG0030532 | BAT-EMI By Band | Reports = Problem on a report of several tests. Bat-Data deletes the current test but does not recreate it. Bug 2111 = Display of strange messages. Adding backup in the test of the mode used during execution. Bug 2112: report generation problem User Story 2094 = Create report template for setup Addition of EMI without band DLLs in the setup for report generation. Bug 2120: BAT-EMI By Band regression: legend of the main graph invisible. | Bug | 3.20.0.0 |
| INC0014065 | BAT-EMC | Problem with auto scale Y for viewing from hardware BAT-EMC | Bug | 3.20.0.0 |
| CHG0030705 | BAT-IMAGE | Added the files that the dockingmanager needs for a default layout | Bug | 3.20.0.0 |
| CHG0030742 | BAT-EMC | PECOS Control Tool Added the message so that user can understand which zone bugged. PECOS Control Tool Corrected a bug occurring when 3 ROI or more were specified. PECOS Control Tool Added a forgotten error management | Bug | 3.20.0.0 |
| INC0014005 | BAT-EMC | Sending the command with start of Write \ 02 and end of write \ 03 | Bug | 3.20.0.0 |
| CHG0030380 | BAT-EMC | Correction of vertical alignment when entering Transient steps | Bug | 3.20.0.0 |

| | | | | |
|------------|-----------|---|-----------|----------|
| INC0014061 | BAT-EMC | Fix the case of objects that cannot be loaded because their idObject is lower than that of their parent | Bug | 3.20.0.0 |
| INC0014050 | BAT-EMC | Problem with the type of fields in g_LabelObjets following the modification to the ticket INC0013731. | Bug | 3.20.0.0 |
| INC0014006 | BAT-EMC | During installation if restarting, a message is displayed to the user | Bug | 3.20.0.0 |
| INC0013581 | BAT-EMC | Issues with lines are highlighted in the equipment script editor (only in release) | Bug | 3.20.0.0 |
| CHG0030466 | METROLOGY | Delete message Scope not found in a specific case | Bug | 3.20.0.0 |
| INC0013986 | BAT-EMC | MXE Driver: - Disable correction factor (correction group OFF) - Read Manual MaxHold Command was wrong | Bug | 3.20.0.0 |
| CHG0030533 | VISU V4 | 2142: CISPR16 recommendation | Evolution | 3.20.0.0 |
| INC0013949 | BAT-EMC | For TCPIP comm only and if no end of string character defined in BAT: VI_ATTR_SUPPRESS_END_EN to false in all cases in TCP | Bug | 3.20.0.0 |
| CHG0030533 | VisuV4 | Simplification of the display of the name of the limits, elimination of all the static part (B2115) | Evolution | 3.20.0.0 |
| CHG0030533 | BAT-EMC | Addition of a menu for the report manual in the help of BAT-EMC | Evolution | 3.20.0.0 |
| CHG0030533 | BAT-EMC | Addition of the manual NewReportGeneration_EN.pdf in the setup | Evolution | 3.20.0.0 |
| CHG0030533 | BAT-EMC | Add a new console application project to generate documentation containing all report tags | Evolution | 3.20.0.0 |
| CHG0030533 | VisuV4 | Removal of Nexio.Bat.Emi.VisuV4.Theme.VS2013 | Bug | 3.20.0.0 |
| CHG0030380 | BAT-EMI | Improved reporting | Evolution | 3.20.0.0 |
| CHG0030380 | BAT-EMI | Strange message display. Adding backup in the test of the mode used during execution | Bug | 3.20.0.0 |
| CHG0030466 | METROLOGY | Bug 2088: The limits and uncertainties of metrology are displayed in the other sub-bands of the BAT-FT tests | Bug | 3.20.0.0 |
| CHG0030532 | METROLOGY | Template Metrologie Scope: 2094 - create report template for setup. User Story 2095: create template in the setup. Adding Metrology VNA template | Bug | 3.20.0.0 |
| CHG0030553 | BAT-EMC | Correction SQL request for tooltip include / exclude table | Bug | 3.20.0.0 |

| | | | | |
|------------|----------|--|-----------|----------|
| CHG0030755 | BAT-EMC | AudioBreakThrough module | Evolution | 3.20.0.0 |
| INC0013460 | BAT-EMC | Execution time is not correct for radio sensitivity tests | Bug | 3.20.0.0 |
| INC0013647 | BAT-ELEC | Standard 7637-3 | Evolution | 3.20.0.0 |
| INC0014117 | BAT-EMC | EOS char was staying in the buffer and shifted all read commands (tested on PXE) | Bug | 3.20.0.0 |
| INC0013834 | BAT-EMC | Case conversion problem Test conducted current with setpoint in conducted power | Bug | 3.20.0.0 |
| INC0014045 | BAT-EMC | Problem with report tag "RegulParam" | Bug | 3.20.0.0 |
| INC0014121 | BAT-EMC | ESU_LAN receiver driver has to use ESU.dll instead of ESU_LAN.dll (out of date) | Bug | 3.20.0.0 |
| INC0014117 | BAT-EMC | EOS char was staying in the buffer and shifted all read commands (tested on PXE) | Bug | 3.20.0.0 |

| | | | | |
|------------|---------|--|-----|----------|
| INC0014104 | BAT-EMI | RE with Automotive Bands Report Template. Addition of the name of the polarization above the graphs | Bug | 3.20.0.0 |
| INC0013853 | BAT-EMC | Crash bat-visu3 (disable database pooling) | Bug | 3.20.0.0 |
| INC0014079 | BAT-EMC | Display problem following INC0013581 Many lines are highlighted in the equipment script editor | Bug | 3.20.0.0 |
| INC0014063 | BAT-EMC | Correction of infinite loop in reverb when the option "Multiple modulations / Successive application" is checked (Procedure tab in sub-bands) | Bug | 3.20.0.0 |
| INC0013970 | BAT-EMC | Driver problem the command is correct but for this equipment (MSO54) you must put the complet command and not the short one : MEAS:IMM:TYPE FREQ is not working MEASUREMENT:IMMED:TYPE FREQUENCY Works | Bug | 3.20.0.0 |